Instruction Manual Counter M



1. This counter is packed in 2 bags. One for the base 2. and tabletop, and one for the wrap (incl. print).



Place the base on the floor, with the white side with plastic feet down.



3. To attach the wrap, start at one side of the hook Velcro strip.



4. Attach the print until you're half way.



5. Then slide in the table top so it leans on the curve of the wrap, and the Velcro connects.



table top, until it's attached all the way.



6. Continue to attach the wrap around the base and 7. The counter is now ready to use, and can hold up to 50 Kg.



To disassemble; open the counter half way and take off the table top.



Now you can take the print off completely, and store the parts in the separate bags.




Make sure you roll up the wrap with the print on the outside, for longer durability.



Scan for instructional video



Optional: Shelf



2 in the front and 2 in the back.

Slide the pins in the grooves. Keep them vertical, so you don't damage the print on the other side.

Open the counter slightly, to create more working space for the pins in the front.



4. Place the hook between the 2 pins on the left side, connecting them together.



on the left side.



5. Slide in the shelf and place it on top of the hook 6. Now lift the right side of the shelf and place the 7. The shelf is now in position and can hold up hook between the 2 pins on the right side.



to 10 Kg.



Pin



